Navajo Abandoned Uranium Mine

Site Screen Report

This form is for use at the site of abandoned uranium mines (AUM) located on Navajo Nation lands. Applicable sites include all mine and mine features that have or have not undergone reclamation by the Navajo Abandoned Mine Lands Reclamation Program, including features, adits, pits and waste piles. Applicable sites also include all AUM sites listed in the USEPA CERCLIS database, all sites listed in the 2008 AUM GIS Report issued by USACOE and USEPA, all AUM sites on allotment lands associated with the Navajo Nation, and any and all AUM sites not listed in any database located on Navajo lands. Reconnaissance of any sites located on lands adjacent to Navajo lands that may be impacting Navajo lands will need to be coordinated with the authorities appropriate to those lands.

The purpose of the form is to ascertain the status and location of the identified AUM site, and record all immediate site information associated with the mine site. Decisions and recommendations on what additional steps are needed will be provided on a separate document.

Cov068 AUM Site

Navajo AUM Northern Region

Prepared by:

Weston Solutions, Inc.

Contract: W91238-06-F-0083

12767.063.496.1111

March 2010

Part I Site Identification, Location and Status Site Names and ID numbers as applicable **Mine ID:** 420 Map ID: N218 **CERCLIS:** NNN000908885 Navajo Abandoned Mine Land Reclamation Program: None Local name / Aliases: None **Chapter and local area:** Cove Chapter County: Apache State: Arizona **Lat/Long:** 36.532027006 N / -109.24470092 W **Nearby road and highway:** Indian Route 33 Local Post Office: Cove, AZ Surface Land Status: check one or more and provide ownership and contact information below **Tribal Trust Land Public lands Private Tribal Fee Land Bureau of Land Mgmt Allotment** Fee land State **Subsurface Mineral Rights:** No information on subsurface mineral rights ownership was found in the EPA/AUM Database. **Claim and operator information:** The mine site surface land status is classified as Tribal Trust Land. No other historical ownership / lease information was identified in the EPA/AUM database. Number of residential structures within 200 feet of mine: None **Estimated volume of mine waste onsite:** 107 yd^3

Part II Summary of radiological readings

Highest gamma radiation measurement:

353,622 counts per minute (cpm)

Describe any other radiological measurements:

A total of 1,337 gamma radiation measurements were collected from the mine site, ranging from 7,536 cpm to 353,622 cpm. Measurements in the vicinity of the waste debris south of the site boundary were found at levels of approximately 160,000 cpm, and in the pile at the southern portion of the site at approximately 220,000 cpm. The measurements are represented in Figures 1 and 2.


Background Locations

Average background = 8,735 cpm

#1 7,788 cpm #2 9,805 cpm #3 8,612 cpm

Distribution Chart and Statistics:

The following chart and statistics were generated by ESRI ArcGIS 9.3.1, and show the general distribution of the site gamma radiation measurements. The horizontal X axis represents the gamma radiation reading levels in cpm (lowest levels to the left). The vertical Y axis represents the frequency of each gamma radiation level.



 Count:
 1337

 Minimum:
 7536,00000

 Maximum:
 353622,00000

 Sum:
 76789932,00000

 Mean:
 57434,50411

 Median:
 44827,00000

 Standard Deviation:
 62801,61695

Part III Status of Reclamation and Mine Waste

The following information was obtained from the Navajo Abandoned Mine Land Reclamation Program (NAMLRP) Point Features Database:

NAMLRP Status of the mine site: Reclaimed : No Waste Pile onsite : No

NAMLRP Project Number: None

NAMLRP Mine features: 1 Rim Strip / Pit

The following information was obtained from field observations collected during the 2009 site screening:

Provide description and status of all mine sites and features at site. Include all waste piles, adits, pits and other features, and indicate whether they are open, closed, covered, capped, buried or unreclaimed. Indicate approximate size, shape and extent, including description of any reclamation caps. Note condition of all caps.

\mathbf{O}	bserved	reclan	nation	work	and	ctatu	c ·
\ //	DSELVEU	Teclat	HALIOH	WUIK	anu	SIALL	҈.

Adits

None

Waste Piles

Two debris piles observed approximately 80 ft apart: 5' x 15'; 5' x 20'; with a total estimated volume of 107 yd³

Pits

None

Shafts

None

Other Debris and Mine Features

None

Part IV

Site observations and Environs

Observed Structures: list number of and describe human habitation status of structures at the following distances from mine:

0 to 200 feet: None

200 feet to 0.25 mile: None

Observed Public or commercial structure: list and describe all schools, clinics, Chapter Houses, places of business and any other structure used by members of the community at the following distances:

0 to 200 feet: None

200 feet to 0.25 mile: None

Levels measured around the perimeter(s) of the identified structure(s):

None

Observed water sources: list the number and type of wells and surface water sources that are potentially used for human consumption at the following distances from the mine:

0 to 0.25 miles: None

0.25 miles to 4 miles: None

Sensitive environments: note and describe all sensitive environments located within visible range of the mine site, including: wetlands, endangered species, habitats and approximate locations of sites that may be under protection of the government of the Navajo Nation.

None observed

Known Site History: include information from interviews with Chapter officials and residents. Note information on mine ownership, type of mining operation, period of operation, known amount of production, and any other information as provided.

Cov068 mine consists of an area of 11,664.86 m². The mine was not identified as ever being operational. No other historical information or any additional ownership / lease information was identified in the EPA/AUM database.

Part V Response Action Summary

Site Name(s): Cov068 **Chapter:** Cove

Decision Criteria

Is there an unreclaimed waste pile at the site? Yes

At what distance from the waste pile is the nearest residential structure located? None

At what distances from the waste pile are there potential drinking water sources? None

Is there a reclamation cap or sealed adit in place at the site? None

Is the cap/seal functionally intact? None

Is the cap/seal sufficiently degraded to create a concern about releases? No

At what distance from the cap/seal is the nearest domestic structure located? None

At what distance from the cap/seal is the nearest domestic drinking water source? None

Summary of emergency response factors

None

Summary hazard ranking system factors

None

Summary of reclamation factors

2 unreclaimed waste piles

Part VI Photos



Photo 1. Pathway leading into mine site



Photo 2. Waste pile south of site boundary



Photo3. Waste pile in southern portion of site




Photo 4. Steep grades on all sides of site

Part VII **Contacts Reports and Information**

Name:	<u>Stanley Edison</u> (928) 871-6861							
	Eugene Esplain (928) 871-7331							
Title or o	fficial role (if any) Navajo EPA Superfund Program							
Address PO Box 2946, Window Rock, AZ 86515								
Information provided <u>Lead Regulatory Agency</u>								
Name								
Title or official role (if any)								
Address								
Telephone number								
Information provided								
Name								
Title or official role (if any)								
Telephone number								
Information provided								
Name								
Title or of								
Telephone								
Informati	on provided							

Figure 1 - Gamma Radiation Measurements, Above Two Times Background
Cov068 (420)
Cove Chapter, Navajo Nation, Arizona



Gamma Radiation Measurements

- < 2X Backgound</p>
- > 2X Background

Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 8,735 cpm



Observed Waste Pile




General Direction Down-Slope



Mine Claim Boundaries



Figure 2 - Gamma Radiation Measurements Cov068 (420) Cove Chapter, Navajo Nation, Arizona



Legend

Gamma Radiation Measurements

- 0 10,000
- 10,000 15,000
- 15,000 20,000
- **2**0,000 50,000
- 50,000 100,000
- > 100,000



→ General Direction Down-Slope



Gamma survey conducted 10/2009 Measured as counts per minute (cpm)

Average background = 8,735 cpm

